



OFFICIAL TWEET
OF THE U.S. IBWC

INTERNATIONAL BOUNDARY AND WATER COMMISSION UNITED STATES AND MEXICO

Status of Tijuana Infrastructure

September 9, 2022 1:35 p.m.

Status of Tijuana River Infrastructure

We are now experiencing transboundary flows at the Tijuana River due to the rains south of the border.

The sediment berm for containment of dry weather flows has been breached.

Transboundary flow started at 10:00 this morning. Current flow is registering at over 300 million gallons per day (MGD) with total volume so far of 11.7 MG.