





USIBWC ~ LRGFCP


Floodgates





MFS1-77
 Sta 1007+39.50
 Off 1.02 LT
 ELEV.90.47
 X=1129817.96
 Y=16557402.13

LOCATION of FLOODGATES







Mercedes Floodgates - North Floodway

500 m
2000 ft

FLOODGATE



FLOODGATE COMPONENTS



GATE UNIT:

The entire structure, including the gate, gate pan, installation bracket, and wiper walls (not shown here).

FLOODGATE Maintenance – Lifting the Gate Panels



FLOODGATE Maintenance – Lifted Gate Panels





FLOODGATE Maintenance – Cleaning Gate Pan






Completed Floodgate Maintenance





**JACKSON ROAD LOCATED IN MCALLEN AT INTERSECTION WITH
MAIN FLOODWAY NORTH AND SOUTH LEVEE**



Damaged Floodgate @ Jackson Road

11/13/2017



Traffic Control @ Jackson Road



Damaged Floodgate Removed



Placing 1" Steel Plates to Cover Gate Pan



Securing The 1" Steel Plates Across Jackson Road



Floodgate Repairs



Floodgate Repairs



Placement of New Gate



Finished Floodgate Repair @ Jackson Road

